



Former Denow Landfill - Groundwater Monitoring

Well Identification	Approximate Distance and Direction from Former Landfill (in feet)	General Contaminant Concentration Trend	Date Last Sampled	Contaminants Concentrations Above State Limits?
Groundwater Monitoring Wells				
MW-1S	140 North	Increasing	Sep-2006	Yes
MW-1B	140 North	Decreasing/Stable	Sep-2006	Yes
MW-1D	140 North	Not Detected	Sep-2006	No
MW-2S	90 South	Decreasing/Stable	Sep-2006	Yes
MW-2D	90 South	Increasing	Sep-2006	Yes
MW-3S	15 East	Increasing	Sep-2006	Yes
MW-3D	15 East	Decreasing	Sep-2006	Yes
MW-4S	60 East	Not Detected	Apr-2001	No
MW-4D	60 East	Not Detected	Apr-2001	No
MW-5S	610 East	Not Detected	Apr-2001	No
MW-5D	610 East	Not Detected	Sep-2006	No
MW-6S	780 Southeast	Not Detected	Apr-2001	No
MW-6B	780 Southeast	Stable	Sep-2006	Yes
MW-6D	780 Southeast	Stable	Sep-2006	Yes
MW-7S	1,330 Southeast	Not Detected	Apr-2001	No
MW-7D	1,330 Southeast	Not Detected	Apr-2001	No
MW-8S	15 South	Decreasing/Stable	Sep-2006	Yes
MW-8B	15 South	Decreasing	Sep-2006	Yes
Former Private Water Supply Wells				
2224 Edgewood Drive	2,360 Southeast	Not Detected	Sep-2006	No
2232 Edgewood Drive	2,310 Southeast	Not Detected	Sep-2006	No
2267 Edgewood Drive	1,660 Southeast	Stable	Sep-2006	Yes
2280 Edgewood Drive	1,340 Southeast	Decreasing	Sep-2006	Yes
In-Use Private Water Supply Wells				
1754 Hillside Court	2,330 Southeast	Not Detected	Sep-2006	No
1769 Hillside Court	2,040 Southeast	Not Detected	Sep-2006	No
1774 Hillside Court	2,150 Southeast	Not Detected	Sep-2006	No
2131 Green Bay Road	3,700 Southeast	Not Detected	Sep-2006	No
2165 Green Bay Road	3,450 Southeast	Not Detected	Sep-2006	No
2217 Green Bay Road	3,550 Southeast	Not Detected	Sep-2006	No
2225 Green Bay Road	3,600 Southeast	Not Detected	Sep-2006	No
1670 Pleasant Valley Road	3,500 Southeast	Not Detected	Sep-2006	No
1807 Cedar Sauk Road	650 Northeast	Not Detected	Sep-2006	No